Work Order ID 7 Friday, June 10, 2011 2:51	0517 :23 PM						Page 1
Item ID: D3529-1 Revision ID: Item Name: Bearpaw			Accept		s s	Setup Start Stop	
Start Date: 6/10/2011 Required Date: 6/15/2011 Reference:	Start Qty: 4.00 Req'd Qty: 4.00			Cust Item ID: Customer:			
Approvals: Process P QC:	lan:	Date: //-0/4/3	Tooling: SPC (Y/N):	Date:	F	Run Start Stop	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID Tool # Plan Code	Accept Qty		Reject Insp. Number Stamp
Draw Nbr Ro	evision Nbr	***************************************					
D3529 Re	v A						
110 Waterjet FLOW CNC Waterjet	FLOW WATER JET  Memo  CUT BLAN	NK AS PER FILE D3529-1BI	0.00 0.00 LANK		_6 (	1-6-14	
							4)
120 	HAAS CNC VERTICAL	L MACHINING #1	0.00	last F.K. 11/09/14	4	Ø	
HAAS CNC vertical machine #1	1-Inspect m	naterial for defects or damage 5 and Dwg D3529□3-Deburn	prior to machining □2	-Machine as per			
130 OC	QC2- Inspect parts off n	nachine FAI/FAIB	0.00	/and /F.K. 71/09/14	4	_J	

0.00

Memo

Quality Control

W/O:			V	ORK ORDER CHANGE	ES				• • • • • • • • • • • • • • • • • • • •
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
			- 112					Prod Mgr	
									1
Part No	<b>:</b>	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	<b>A</b> :	_ Date: _	<u>.                                    </u>
·	R	esolution:	_ Disposit	ion:	_ QA: N/C C	osed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	k Sect	ion C	Chief Eng	QC inspector
	1								
								. "	
									;
									-
			·						
1						1		1	

Work Orde Friday, June 10,												Page 2
Revision ID:	D3529-1 Bearpaw			Accept					Setup	Start Stop		
	6/10/2011	Start Qty: 4.00 Req'd Qty: 4.00			Cust Item I Customer:	D:				•	د مان	
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ite:			Run	Start Stop		
Sequence ID/ Work Center ID	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
140 QC		QC8- Inspect parts - seco	nd check		- 11-09-15						1712.9. 1	- <u> </u>
Quality Control		,						e e e e e e e e e e e e e e e e e e e	· .		· · · · · · · · · · · · · · · · · · ·	
150 Packaging Packaging		Identify as per dwg & Sto  Memo	ck Location:	0.00			5	<b>﴾</b> (1	- <u>0</u>	j- 18	·	
160    <b>                   </b> QC		QC21- Final Inspection -	Work Order Release	0.00					···	N	191	16 \$

Quality Control

MF,1.09-15

	Paoc								
W/O:			W	ORK ORDER CHANGES	S				1
DATE	STEP	PRO	OCEDURE CH	Ву	Date	Qty	Approval Chief Eng./ Prod Mgr	Approval QC Inspector	
•									
						···			
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date:	
Resolution:			Dispositi	on:	QA: N/C Clo	sed:		Date: _	
NCR:			WORK ORE	DER NON-CONFORMAN	ICE (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
DAIL	J. L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	ion C	Chief Eng	QC Inspector
						•			
1									

# \*Picklist Print

Friday, June 10, 2011 2:51:28 PM

Work Order ID: 70517

Parent Item:

D3529-1

Parent Item Name: Bearpaw



Start Date: 6/10/2011

Required Date: 6/15/2011

Page 1

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP Rev:A New Issue 06-06-28 JLM

IPP Rev:B New Manufacturing Method 08-11-27 Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MUHMWB10		Purchased	No			100	sf	300.6000	1.265	5.326310		٠ عـ ا	10

UHMW 1" Black

LocationLoc QtyLoc CodeMAT018300.611732176.611773859117819165

4

Dail Aci	ospace	Liu					•			
W/O:			V	VORK ORDER CHANG	GES			7		
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				*						
									· · · · · · · · · · · · · · · · · · ·	
			Fault Category: N			: Yes 1	No DQA	\:	_ Date: _	
	R	esolution:	_ Disposit	ion:	QA:	N/C Clo	sed:		Date:	
NCR:			ORK OR	DER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC	Initial Action Description			Sign & Verification Control			Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
				***					A Mary Company of the	·
					·					
									·	
		•		·						

DART AEROSPACE LTD		Work Order:	70517
Description: Bearpaw		Part Number:	D3529-1
	***		-
Inspection Dwg: D3529 Rev	: A		Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	spection Sheet wing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Α	5.50	+/-0.030	5.501				
В	0.07 x 45°	+/-0.030 x 0.5°	24,280.	······································		_ ;	
С	R0.25	+/-0.030	.25				
D.	0.250	+/-0.010	.251				
E	0.625	+/-0.010	. 626				
F	0.950	+/-0.010	.951	,			
G	1.63	+/-0.030	1.619				
Н	12.14	+/-0.030	12.142				
, I					·		
J	5.70	+/-0.030	5.70				-41
K	0.375	+/-0.010	.375				
L	0.525	+/-0.010	. 5.30				•
М	0.13 x 45°	+/-0.030 x 0.5°	.160				
Ν	R0.50	+/-0.030	,50				
0	12.76	+/-0.030	12.766				
Р	3.38	+/-0.030	3,3795	***			, ,,
Ø	3.75	+/-0.030	3,757				V
R	5.187	+/-0.010	5. 187				· · · · · · · · · · · · · · · · · · ·
S	5.25	+/-0.030	5.255				
Т	7.13	+/-0.030	7,13				
U	Ø0.260	+0.006/-0.001	.Z60				
<b>\</b>	0.30	+/-0.030	. 299	,			
W	0.93	+/-0.030	,925				
Χ	1.30	+/-0.030	1.30				


Measured by:	K. / and	Audited by:	-SL	Prototype Approval:	N/A
Date:	11/09/14	Date:	11-09-15	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.05.01	New Issue	KJ/JLM 140	
В	08.05.06	Dimension I removed	KJ/DD O	7

	•								
W/O:	WORK ORDER CHA				ES				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									Ē
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:	
		esolution:							
NCR:		\	WORK ORD	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC Corrective Action			Section B Verif			Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
					· ·				
1	1		l i		i i	1		I	1







### **D3529-1 R44 BEARPAW**

#### NOTES:

- 1) MATERIAL: UHMW BLACK PER SPEC CONTROL DRAWING D2689, 1.00 THICK (MACHINE TO 0.950)

- 2) FINISH: NONE
  3) PART IS SYMMETRIC ABOUT €
  4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
  5) ALL DIMENSIONS ARE IN INCHES

- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX
  7) ENGRAVE LOGO TO MAX DEPTH OF 0.012 AT LOCATION SHOWN
  8) ENGRAVE PART AND BATCH NUMBERS TO MAX DEPTH OF 0.010 AT LOCATION SHOWN


### **COPYRIGHT © 2007 BY DART AEROSPACE LTD**

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	Topaso										
W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO	OCEDURE CHA	NGE	E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:	Fault Cate	egory:	NCR:	Yes N	o <b>DQ</b>	<b>A</b> :	: Date:		
Resolution:			Disposition	n:	QA: N	/C Clos	sed:		Date: _		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (	NCR)					
DATE	STEP	Description of NC			Section B Verific			ation	Approval	Approval	
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	. QC Inspector	




CB	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
CHECKED	APPROVED	DRAWING NO.	REV. A			
1		D3329	SHEET 2 OF 2			
07.01.04		TITLE	SCALE			
		R44 BEARPAW	1:4			



**SECTION A-A** 

**SECTION B-B** 

SECTION C-C



	Johnson								
W/O:			WC	RK ORDER CHANGE	S		<u>. –                                     </u>		
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							<u> </u>		
							ŀ		
Part No: PAR #:		PAR #:	Fault Cate	NCR: Yes	CR: Yes No DQA: Date:				
		Disposition	QA: N/C CI	A: N/C Closed:			Date:		
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification		Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	ion C	Chief Eng	QC Inspector
:	. ¥ v.								
					; ;				
								-	